Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number

 ID1159
 MANHOLE 38640
 NY Spills
 S104284092

 NNE
 MCDONALD AVE/ AVE S
 N/A

> 1 BROOKLYN, NY

1.528 mi.

8067 ft. Site 1 of 2 in cluster ID

 Relative:
 SPILLS:

 Higher
 Name:
 MANHOLE 38640

 Actual:
 Address:
 MCDONALD AVE/ AVE S

 22 ft.
 City,State,Zip:
 BROOKLYN, NY

Spill Number/Closed Date: 9909984 / 2002-03-29

9909984 Facility ID: Facility Type: ER DER Facility ID: 166341 199888 Site ID: DEC Region: 2 Spill Cause: Unknown Spill Class: C4 2401 SWIS: Spill Date: 1999-11-17 Investigator: COMENALE Referred To: Not reported Reported to Dept: 1999-11-17

CID: 382 Water Affected: Not reported Spill Source: Unknown Spill Notifier: Other Cleanup Ceased: Not reported Cleanup Meets Std: False Last Inspection: Not reported Recommended Penalty: False **UST Trust**: False Remediation Phase: 0

Date Entered In Computer: 1999-11-17
Spill Record Last Update: 2002-03-29
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported

Spiller Company: 999

Contact Name: STEVEN CRIBBIN

DEC Memo:

Remarks: "SHEEN ON 200 GALS OF WATER IN MANHOLE. CLEAN UP PENDING. CON ED

129-024"

All Materials:

 Site ID:
 199888

 Operable Unit ID:
 1088672

 Operable Unit:
 01

 Material ID:
 555940

 Material Code:
 0066A

Material Name: unknown petroleum
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00

Oxygenate: Not reported